

14.02 Firmware Release for RCC Product

Summary

Horner APG announces the availability of Firmware Revision 14.02 for the RCC controller. This is available for download from the firmware section of the US web site, <https://www.heapg.com/support/controller-firmware/> or the European web site, <http://www.horner-apg.com/en/download/ocs.aspx>

A NOTE ABOUT FIRMWARE UPDATES:

This firmware has been thoroughly tested, and every precaution has been taken to prevent the introduction of new issues that may be problematic in your application. It is always important for customers to perform their own internal system testing prior to deployment of new firmware.

Factory Revision Letter for the Last Released Version of Product (Pre 14.02)

Product	Revision Letter (Note the second letter indicates Firmware Revision)
HE-RCC972	AD

Firmware 14.02 Enhancements – Feature Enhancements

Feature Enhancements	
1.	CsCAN Networking Blocks in IEC61131 with Arrays of Structure
2.	Passive FTP Mode
3.	Long File Name Support
4.	Full Support of Smart Block Family
5.	Hardware Handshaking Support

Firmware 14.02 – Issues Resolved

Issues Resolved	
1.	32 Bit Counter Passing Power Before Reaching the Set-point when the Reset is Enabled
2.	Schedule Objects in Ladder not Passing Power when Set to Registers

North America:

Tel: (317) 916-4274
 Fax: (317) 639-4279
 Web: <http://www.heapg.com>
 Email: techsppt@heapg.com

Europe:

Tel: +353 (0)21 4321 266 Ext 202
 Fax: +353 (0)21 4321 826
 Web: <http://www.horner-apg.com>
 Email: technical.support@horner-apg.com